

A 0374 + BMWF650GS/800

Kanto Ranked

Inspection completed

Frame No. WB10218089ZT36473		Color	RED	Number Plate	
Engine Model 802EA 08548546		Displacement	800cc	Starting Bid	
Meter	70,149K	Year	H21	BID	<input type="button" value="Sold"/>
Meter of Public Vehicle inspection	67,500K	Registration	R 6/ 4		
Meter history of past		Genuine Parts	No Part		

## Sales Data

【BMW650GS/800】  
Rank 4 bikes Monthly Sales Data Sold 1 bikes in the range

## BDS Comment

全体キズ、サビ、変色。外装変色大。

## Seller Comment

Rank	Engine	Front	Exterior	Rear	Electronic Safety Parts	Frame
4	3	4	3	4	5	4



Engine:3

Front:4

Engine	EngineNoiseLv3 Rust Puffed smoke	Tube outer	OuterFlawLv3 Seal failure
Crankcase cover	CoverFlaw	Tube inner	InnerRust
Oil leak		Stem steering	
Radiator	RadiatorRust	Steering handle bar	HandleRust,End-partShaved,CoverPartial paintLv3failure FlawLv3,PostNot Genuine product
Carburetor		Front Wheel	WheelFlawLv3 Rust
Clutch		Front Brake	BreakDiskRequired replacement
Starting motor		Front Tire	TireDecreased or Crack

Exterior:3

Rear:4

Upper cowl	UpperFlawLv3	Rear shock	ShockRust
Center cowl	CenterFlaw	Swing arm	SwingarmFlaw Rust
Under cowl		Chain	ChainRust
Side cowl	SideFlaw	Sprocket	
Tank fuel	TankFlawLv3	Rear Wheel	WheelFlawLv3 Rust
Seat		Rear Brake	BreakRust
Tail cowl	TailFlawLv3	Rear Tire	
Front fender	Front-fenderFlaw		
Rear fender			
Screen	ScreenFlaw Not Genuine product		

Electronic Safety Parts:5

Frame:4

Key	Key1	Mainframe	Main-frameFlaw RustLv3
Meter	LensCrackLv1	Downtube	
Turn-signal	Turn-signalCrack ShortageLv1	Stopper	
Headlamp		Seatrail	SeatrailFlaw
Battery		Step	StepFlaw Rust BendLv1
Horn		Stand	StandFlaw Rust Shaved Treatment
Back-lamp			
Mirror	MirrorFlaw		
Silencer	SilencerFlaw		
Exhaustpipe	Exhaust-pipeRust		