

D 7703 Y MT-07

Kanto

Ranked

Inspection completed

Frame No. RM07J-000027		Color	WHITE	Number Plate	
Engine Model M403E-000028		Displacement	700cc	Starting Bid	
Meter	41,775K	Year	H26	BID	<input type="button" value="Sold"/>
Meter of Public Vehicle inspection	40,400K	Registration	R 6/ 9		
Meter history of past		Genuine Parts	No Part		

Sales Data

【MT-07】

Rank 4 bikes Monthly Sales Data Sold 6 bikes in the range

BDS Comment

各所变色。

Seller Comment

Rank	Engine	Front	Exterior	Rear	Electronic Safety Parts	Frame
4	4	4	5	4	4	4



Engine:4

Front:4

Engine	EngineRust,UnderFlawLv3 Partial paint	Tube outer	OuterFlawLv3 Partial paint Shaved Oil leakLv1
Crankcase cover	CoverFlawLv3 Rust	Tube inner	
Oil leak		Stem steering	StemRust
Radiator	RadiatorRustLv3,FinDent,HoseFlaw Partial paint	Steering handle bar	End-partNot Genuine product,LeverNot Genuine product,GripNot Genuine product
Carburetor	CabRust	Front Wheel	WheelFlaw Rust
Clutch		Front Brake	BreakRust Diskworn-down
Starting motor		Front Tire	TireReduceRequired replacement

Exterior:5

Rear:4

Upper cowl		Rear shock	ShockRustLv3
Center cowl	CenterFlawLv3 Shaved	Swing arm	SwingarmFlaw Rust
Under cowl		Chain	ChainRust
Side cowl		Sprocket	
Tank fuel	TankFlaw,PatInstalled	Rear Wheel	WheelFlawLv3 Rust
Seat		Rear Brake	BreakRust
Tail cowl	TailFlaw	Rear Tire	TireReduce
Front fender	Front-fenderFlaw		
Rear fender	Rear-fenderFlaw		
Screen	ScreenFlaw		

Electronic Safety Parts:4

Frame:4

Key	Key3	Mainframe	Main-frameFlaw Rust
Meter		Downtube	
Turn-signal	Turn-signalFlaw Not Genuine product	Stopper	
Headlamp	HeadlampFlaw,InnerNot Genuine product	Seatrail	SeatrailRust
Battery		Step	StepFlawLv3 Bend Rust
Horn		Stand	StandRustLv3
Back-lamp	Back-lampFlaw		
Mirror	MirrorFlaw		
Silencer	SilencerRust,CoverFlawLv3 Dent		
Exhaustpipe	Exhaust-pipeRustLv3		